



PLATE O

<u>Part</u>	<u>BMC #</u>	<u>Other #</u>	<u>Plate</u>	<u>Item</u>	<u>Also Fits</u>	<u>Vendor</u>
Tap - Cylinder Drain	2H764		O	1	AH BN1 & BN2	www.mossmotors.com
Washer for tap - 1/16" thick - fibre	2K4954		O	2	AH 3000 (Series BN7 and BT7)	www.mossmotors.com
Washer for tap - 1/32" thick - fibre	2K4975		O	--	AH 3000 (Series BN7 and BT7)	www.mossmotors.com
Bracket for Dynamo	2A758		O	3	AH Sprite 948 (with Dynamo)	None Found
Nut for Dynamo Bracket Stud	FNZ105		O	4	5/16" UNF Std. Hex Nut	N/A
Washer for Stud	LWZ205		O	5	5/16" Zinc Spring Washer	N/A
Pillar - Mounting Adjustment Link	10K82		O	6	None Found	None Found

SERVICE PARTS LIST

GIPSY

DESCRIPTION	Commencing E.101		Qty. per Vehicle		Unit of issue	Type of Vehicle	MODIFICATIONS			REMARKS
	Part Number	Illus. No.	RHD	LHD			New Part Number	Change Point	Amendment No.	
<i>Diesel Engine—continued</i>										
DRAIN TAP										
Tap—cylinder drain.....	2H764	O1	1	1						
Washer for tap ($\frac{1}{8}$ " thick)—fibre.....	2K4954	O2	1	1						} Optional thickness to determine position.
Washer for tap ($\frac{1}{16}$ " thick)—fibre.....	2K4975		1	1						
DYNAMO BRACKET										
Bracket for dynamo.....	2A758	O3	1	1						
Nut for dynamo bracket stud.....	FNZ105	O4	2	2						
Washer for stud (spring).....	LWZ205	O5	2	2						
Pillar—mounting (adjusting link).....	10K82	O6	1	1						